



State of UtahDEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Supervisor

Minerals Regulatory Program Date of Report: August 2, 2010

Mine Name: Bromide Basin

Operator Name: Bromide Mining LLC

Permit number: S0170031 **Inspection Date:** July 27, 2010

Time: 12:30-2:30 PM

Inspector(s): Wayne Western

Other Participants: Buzz Racko - BLM, Kathy Anders - BLM, Sakkie Eichorn - Permittee, Shane

Scott - BLM

Mine Status: Inactive Weather: Partly cloudy to rain, 80s

| Evaluated | Comment | Enforcement |
|-----------|-----------|-------------------|
| | | |
| | | \boxtimes |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | $\overline{\Box}$ |
| | | |
| | Evaluated | |

Purpose of Inspection:

This was a routine inspection.

Inspection Summary:

1. Permits, Revisions, Transfer, Bonds

The Permittee posted a \$25,000 bond that is due for Renewal on July 15, 2012. The Permittee agreed to conduct a survey to determine if they were operating within the permit area.

The Permittee is conducting exploration activities.

2. Public Safety (shafts, adits, trash, signs, highwalls)
The mine has three portals they have been gated to prevent access.

Page 2 of 2

Inspection Date: July 27, 2010

S0170031

4. Deleterious Material

The site had been clean up. In the 2008 inspection report mention is made of trash on site. The Division's camera was not working.

Conclusions and Recommendations:

The Permittee committed to conduct a GPS survey to determine if they were operating within the permit area. The Division was asked to attend a meeting with company official in August. The Division should sent a representative.

Date: <u>8/2/2010</u>

Inspector's Signature Mayne When term

WHW:pb

ee 1

Bromide Mining LLC

Buzz Rakow, Hanksville BLM

O:\M017-Garfield\S0170031-Bromidebasin\inspections\ins-07272010.doc